



insider info.

Keyless Entry Battery Replacement

After replacing the keyless entry transmitter battery on 1999-2001 Legacy models and 2001 Forester models, the transmitter must be re-synchronized with the vehicle. To re-synchronize the system, simply press either transmitter button (Lock/Arm or Unlock/Disarm) six times.