

insider info.

1995 Legacy Speed Limiting Device

Incorporated in the fuel injection computer logic is an injector cutoff at 113 mph. Since there is no public road in the United States that has a legal speed limit anywhere near that high, this information was not included in the Owner's Manual. From a technical point of view, however, it is good for you to know about it in case of speed sensor malfunction. If the Select Monitor erroneously show a speed of 113 mph or higher, you can expect the injectors to be cut off until the speed-indication on the monitor displays under that speed.