







LH HEADLAMP ASSY

COMPONENTS

6515Q-01





* : When only the installation part of the headlight unit assy LH is damaged, it can be repaired inexpensively by using a bracket provided for repair. In this case, however, the headlight unit assy LH itself should not be damaged.