


NAVIGATION RECEIVER ASSY REPLACEMENT

6719Q-01


HINT:

Installation is in the reverse order of removal.


1. **REMOVE INSTRUMENT CLUSTER FINISH PANEL SUB-ASSY CENTER (SEE PUB. No. RM864E, PAGE 71-10)**
2. **REMOVE INSTRUMENT CLUSTER FINISH PANEL END (SEE PUB. No. RM864E, PAGE 71-10)**
3. **REMOVE AIR CONDITIONING CONTROL ASSY (SEE PUB. No. RM864E, PAGE 55-37)**

**4. REMOVE NAVIGATION RECEIVER ASSEMBLY W/BACKET**

- (a) Remove the 4 screws.
- (b) Disconnect the connectors and remove the navigation receiver assembly w/bracket.

**5. REMOVE RADIO BRACKET NO.1**

- (a) Remove the 4 screws and radio bracket No.1.

**6. REMOVE RADIO BRACKET NO.2**

- (a) Remove the 4 screws and radio bracket No.2.

7. REMOVE NAVIGATION RECEIVER ASSY