

DTC	P0133	Oxygen Sensor Circuit Slow Response (Bank 1 Sensor 1)
-----	-------	--

CIRCUIT DESCRIPTION

Refer to "Insufficient Coolant Temp. for Closed Loop Fuel Control" on page [DI-41](#).

DTC No.	DTC Detecting Condition	Trouble Area
P0133	Response time for the oxygen sensor's voltage output to change from rich to lean, or from lean to rich, is 1 sec. or more during idling after the engine is warmed up (2 trip detection logic)	• Oxygen sensor

HINT:  
Sensor 1 refers to the sensor closer to the engine body.

INSPECTION PROCEDURE

1	Are there any other codes (besides DTC P0133) being output?
---	---

YES

Go to relevant DTC chart.

NO

Replace oxygen sensor.