



**Technical Service
BULLETIN**
May 23, 1997


Title:
**'97 PIO/DIO 34224 FUJITSU TEN CD PLAYER
DOES NOT EJECT / ACCEPT CD**

Models:
All '97 Models

AU003-97

AUDIO

Introduction The PIO/DIO 34224 Fujitsu Ten CD Player's (P/N 08601-00852) circuitry was changed to eliminate "does not eject/accept CD" conditions.



**PIO/DIO 34224 Fujitsu Ten CD
Player Model Number Location**


**Production
Change
Information**

- Production change occurred in February 1997 on CD players starting with serial number A4400001.

**Exchange
Unit
Information**

- Fujitsu Ten began shipping the countermeasured exchange units starting December 1996.
- Countermeasured CD players have a black dot after the Toyota Parts Number.

Countermeasured units have this black dot



Serial Number

Production Date

Index # 047125



Toyota Supports ASE Certification