



Technical Service BULLETIN

July 17, 1998

Title:


VACUUM HOSE PRODUCTION CHANGE

Models:

'98 RAV4

ENGINE
EG009-98

Introduction To minimize moisture retention and improve MAP Sensor operation, the length of the connecting vacuum line has been shortened 10 mm.



- Affected Vehicles**
- 1998 model year RAV4s built after the following VINs have the new style hose installed:
JT3YP10V*W0170362
JT3HP10V*W0154688
JT3HP10V*W7074617
JT3XP10V*W0008479
JT3GP10V*W0018617
JT3GP10V*W7024861

Parts Information

OLD PART NUMBER	NEW PART NUMBER	PART NAME
17341-74750	17341-74751	Hose, Vacuum

Warranty Information

OP CODE	DESCRIPTION	TIME	OPN	T1	T2
N/A	Not Applicable to Warranty	-	-	-	-

Index # 049918



Toyota Supports ASE Certification