

Countershaft

Index



NOTE: The needle bearings are of the same size.



Before assembling, clean all parts in solvent, dry them with compressed air, then coat them with clean oil.

