

Sub-frame



Sub-frame Torque Sequence:

CAUTION: After loosening the rear beam mounting bolts, be sure to replace them with new ones.

