



Troubleshooting

Reference Chart

- Any abnormality must be corrected before continuing the test.
- Because of the precise measurements needed, use a multimeter when testing.

Before performing any troubleshooting procedures check:

- Fuses No. 41 (80 A), No. 39 (50 A), No. 13 (7.5 A), No. 35 (20 A)
- Grounds No. G701, G201, G401
- Cleanliness and tightness of all connectors.

SYMPTOM	REMEDY
Condenser fan does not run at all.	Perform the procedures in the flowchart (see page 22-8).
Compressor clutch does not engage.	Perform the procedures in the flowchart (see page 22-10).
A/C system does not come on (compressor and fan).	Perform the procedures in the flowchart (see page 22-13).