

TRANSMISSION REMOVAL & INSTALLATION - A/T

Article Text (p. 2)

1993 Mazda 929

For Techdoc Ltd.

Copyright © 1997 Mitchell International

Thursday, March 25, 1999 12:14AM

Application	Ft. Lbs. (N.m)
Crossmember-To-Frame Bolt	32-45 (43-61)
Drive Shaft Center Support Bolt	27-38 (37-52)
Drive Shaft Flange Nut	36-43 (49-58)
Exhaust Pipe Nut	30-41 (41-56)
Starter Bolt	23-34 (31-46)
Torque Converter Bolt	25-36 (34-49)
Transmission-To-Engine Bolt	27-38 (37-52)
Transmission Mounting Bolt	40-56 (54-76)
AA	

END OF ARTICLE