


STARTING & CHARGING



PREPARATION

020JH-01

SST

	09249-63010 Torque Wrench Adaptor	GENERATOR ASSY(1AZ-FE)
---	-----------------------------------	------------------------

Recomended Tools

	(09083-00150) Test Lead Set	STARTING SYSTEM(1AZ-FE)
	09216-00021 Belt Tension Gauge	GENERATOR ASSY(1CD-FTV)

Equipment

Service Wire Harness	
Ammeter	
Ohmmeter	
Radiator cap tester	
Torque wrench	
Slide calipers	