


## W/HOLDER ANTENNA ASSY REPLACEMENT

67068-01

HINT:

COMPONENTS: [See page 67-1](#)

### 1. REMOVE MAP LAMP ASSY ([See page 76-23](#))



### 2. W/HOLDER ANTENNA ASSY

- (a) Remove the nut and antenna cord sub-assy.
- (b) Remove the w/holder antenna assy from the body.

### 3. REMOVE ROOF ANTENNA POLE SUB-ASSY

- (a) Remove the roof antenna pole sub-assy from the w/ holder antenna assy.