

DTC	23	Vehicle Speed Signal Abnormal
------------	-----------	--------------------------------------

CIRCUIT DESCRIPTION

See page [DI-316](#).

DTC No.	Detection Item	Trouble Area
23	<ul style="list-style-type: none"> Actual vehicle speed has dropped either by 16 km/h (10 mph) or more below the set speed, or by 20 % or more of the set speed. Vehicle speed sensor pulse is abnormal. (When speed signal is not input to the ECU below 0.2 sec., code will be displayed.) 	<ul style="list-style-type: none"> Vehicle speed sensor Harness or connector in SPD circuit Cruise control ECU

WIRING DIAGRAM

See page [DI-316](#).

INSPECTION PROCEDURE

1	Check vehicle speed sensor (See page BE-35).
---	---

NG

Replace vehicle speed sensor.

OK

Check and replace cruise control ECU
(See page [IN-27](#)).