

<b>DTC</b>	<b>P0121</b>	<b>Throttle/Pedal Position Sensor/Switch "A" Circuit Range/Performance Problem</b>
------------	--------------	--

## CIRCUIT DESCRIPTION

Refer to Throttle/Pedal Position Sensor/Switch "A" Circuit Malfunction on page [DI-36](#).

DTC No.	Detection Item	Trouble Area
P0121	While the vehicle speed drops from 30 km/h (19 mph) or more to 0 km/h (0 mph), the output value of the throttle position sensor is out of the applicable range (2 trip detection logic)	• Throttle position sensor

## INSPECTION PROCEDURE

<b>1</b>	<b>Are there any other codes (besides DTC P0121) being output?</b>
----------	--

**YES**

**Go to relevant DTC chart.**

**NO**

**Replace throttle position sensor.**