



Technical Service BULLETIN

July 28, 2000

Title:

FRONT MUDGUARDS

Models:

'95 – '00 Tacoma 4x4 & PreRunner

BO019-00

BODY

Introduction To help prevent damage to the exterior finish of Tacoma 4x4 and PreRunner vehicles, the front mudguards have been increased in width by 25 mm.

Applicable Vehicles

- 1995 – 2000 model year **Tacoma 4x4** and **PreRunner** vehicles.

Production Change Information

| MODEL | STARTING VIN |
|------------------|-------------------|
| Tacoma 4x4 | 4TAPM62N*YZ653866 |
| Tacoma PreRunner | |

Parts Information

| PREVIOUS PART NUMBER | CURRENT PART NUMBER | PART NAME |
|----------------------|---------------------|--------------------|
| 76621-04030 (RH) | 76621-04040 (RH) | Mudguard, Front RH |
| 76622-04030 (LH) | 76622-04040 (LH) | Mudguard, Front LH |

Repair Procedure

Replace the previous mudguards with the countermeasure mudguards.

Warranty Information

| OP CODE | DESCRIPTION | TIME | OPN | T1 | T2 |
|---------|---------------------------------|------|-------------|----|----|
| 610101 | R & R Front Mudguard Assemblies | 0.3 | 76622-04030 | 95 | 57 |

Applicable Warranty*:

This repair is covered under the Toyota Basic Warranty. This warranty is in effect for 36 months or 36,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.

